

Project Experience

WATER


Desalcott– Trinidad & Tobago



Surface Preparation – handrail #1 MBX bristle blaster, #2 sandpaper, #3 chemical wash

MCU System – Miozinc @ 5-6 mils dft & topcoat @ 2-3 mils dft

After 3 months – No loss of adhesion, corrosion, adhesion or colour failures.
Handrail used to be recoated every months using traditional epoxy coating system.



MCU Coatings –
Local Desalination
Plant

Area – Extreme Salt
Water Environment,
Sodium Hypochlorite
(chlorine bleach), Raw
Salts etc

