

Project Experience

Oil and Gas

IPSL – Trinidad & Tobago



Problem – Failure of traditional epoxy 3 coat system due to severe corrosion from marine atmospheric environment (cooling tower & marine)

Solution – MioZinc Primer & Topcoat @ 8 mils dft total

