

MCU-Coatings can do the job where others fail and our track record is impressive. Trinidad Power Plant

<u>PROBLEM</u> – Condenser Waterbox Recoating – NO time for sandblasting & recoating, Direct Sea water contact, Heavy salts, rust & corrosion, Wet Substrate, Condensate leaks, Confined Space,





<u>SOLUTION</u> –Hand Tool Prep- Primer – Miozinc & Topcoat – Ferroguard @ 5 mil DFT, Quickcure Additive – Full 2 layer cure in 1 hour, Cost – Cheaper than Blasting & recoating



